














# Návod k montáži

<b>A</b>  X1	<b>B</b>  X1	<b>C</b>  X1	<b>D</b>  X1	<b>E</b>  X1	<b>F</b>  X1	<b>G</b>  X1
<b>H</b>  X2	<b>1</b>  M6X18 4 ks	<b>2</b>  M8X25 2 ks	<b>3</b>  1 ks	<b>4</b>  1 ks	<b>5</b>  1 ks	

